

# COLLIER COUNTY WETLAND DETERMINATIONS

**UPLD=Upland**

**NDSP=Needs site plan to determine impacts**

**Permit=Permit Issued for property**

**SPWE=Site Plan Wetland**

**NTST = Not Staked. All four corners and impact areas should be staked.**

**ACCESS = No way to access the site. Please cut an access path and resubmit the determination request.**

**WTLD=Wetland**

**MWET=Map shows wetlands**

**MAUP=Map shows uplands**

**SPUP=Site Plan Upland**

**DITCH = Ditches on site.**

## Strap numbers beginning with 4145-4199

| Folio#      | Unit/Tract | Section             | Determ | Date     |
|-------------|------------|---------------------|--------|----------|
| 41440320008 | U090T003   | E75'                | WTLD   | 9/28/07  |
| 41450360003 | U090T109   | 5ACRES              | SPUP   | 11/19/03 |
| 41450520005 | U090T111   | E180'               | WTLD   | 5/13/04  |
| 41450640008 | U090T112   | E75' OF W150'       | WTLD   | 8/17/04  |
| 41450760001 | U090T115   | LESS W330'          | SPUP   | 7/20/01  |
| 41500440006 |            | 38th Avenue SE      | WTLD   | 3/5/2012 |
| 41500480008 |            | 4165 38th Avenue SE | WTLD   | 3/5/2012 |
| 41500600008 | U091T007   | W180'               | WTLD   | 4/21/04  |
| 41500800002 | U091T009   | W75'                | UPLD   | 1/22/04  |
| 41500960007 | U091T010   | E180'               | WTLD   | 11/15/05 |
| 41501240001 | U091T013   | E180'               | MWET   | 7/24/06  |
| 41501256007 | U091T028   | E105'               | MWET   | 7/24/06  |
| 41501800001 | U091T020   | W75' of E150'       | MWET   | 1/20/05  |
| 41501920004 | U091T022   | W75' of E150'       | WTLD   | 3/30/07  |
| 41502000004 | U091T022   | W180'               | MWET   | 4/25/05  |
| 41502240000 | U091T025   | E180'               | WTLD   | 9/8/01   |
| 41502280002 | U091T026   | E105'               | MWET   | 7/7/04   |
| 41502600006 | U091T028   | W 150'              | MWET   | 12/6/06  |
| 41502640008 | U091T028   | E180'               | MWET   | 3/28/05  |
| 41503200007 | U091T036   | E150'               | WTLD   | 1/16/08  |
| 41503440003 | U091T039   | E75' OF W180'       | WTLD   | 9/8/04   |
| 41503480005 | U091T039   | E150'               | MWET   | 2/10/06  |
| 41503520004 | U091T039   | W105'               | WTLD   | 8/17/04  |
| 41503680009 | U091T041   | W150'               | WTLD   | 8/17/04  |
| 41503920002 | U091T044   | E180'               | WTLD   | 10/6/04  |
| 41504040004 | U091T045   | W75' OF E180'       | WTLD   | 5/22/07  |
| 41504800008 | U091T055   | N150'               | MWET   | 2/10/06  |
| 41504840000 | U091T056   | N105'               | WTLD   | 11/23/04 |
| 41504920001 | U091T056   | S75' OF N180'       | WTLD   | 1/10/05  |
| 41505360000 | U091T062   | S150'               | MWET   | 8/22/03  |
| 41505400009 | U091T062   | S75' OF N150'       | NDSP   | 6/14/04  |
| 41505440001 | U091T062   | N105'               | WTLD   | 11/23/04 |
| 41505560004 | U091T064   | N75' of S150'       | WTLD   | 12/27/05 |
| 41506000000 | U091T068   | S180'               | WTLD   | 4/13/05  |
| 41506120003 | U091T069   | S75'                | WTLD   | 4/3/02   |
| 41506160005 | U091T069   | N180'               | WTLD   | 1/21/05  |
| 41506200004 | U091T070   | N75'                | WTLD   | 8/30/04  |
| 41506280008 | U091T070   | S75' OF N150'       | MWET   | 7/24/06  |
| 41506480002 | U091T073   | N180'               | MWET   | 8/17/05  |

| Folio#      | Unit/Tract | Section          | Determ | Date     |
|-------------|------------|------------------|--------|----------|
| 41506920009 | U091T077   | S150'            | WTLD   | 9/19/02  |
| 41506960001 | U091T077   | S75' OF N180'    | WTLD   | 8/27/01  |
| 41507640003 | U091T083   | FIRST 300'       | NDSP   | 9/9/04   |
| 41507680005 | U091T084   | E75' of W180'    | MWET   | 10/31/05 |
| 41507920008 | U091T085   | E75'             | WTLD   | 9/28/04  |
| 41507960000 | U091T086   | E75'             | WTLD   | 6/27/07  |
| 41508000008 | U091T086   | W180'            | WTLD   | 1/30/07  |
| 41508040000 | U091T086   | W75' of E150'    | MWET   | 2/15/06  |
| 41508080002 | U091T087   | W180'            | WTLD   | 4/28/06  |
| 41508240004 | U091T088   | E75'             | MWET   | 7/24/06  |
| 41508400006 | U091T089   | E75' of W150'    | MWET   | 12/27/05 |
| 41508520009 | U091T091   | E180'            | MWET   | 6/20/05  |
| 41508600000 | U091T092   | E180'            | WTLD   | 1/28/05  |
| 41508840001 | U091T043   | E180'            | MWET   | 10/6/04  |
| 41508960009 | U091T095   | W75'             | WTLD   | 6/26/07  |
| 41509280005 | U091T098   | W75' of E150'    | MWET   | 11/15/05 |
| 41509320004 | U091T099   | W180'            | WTLD   | 12/18/06 |
| 41509440007 | U091T100   | E150'            | NAP    | 9/17/07  |
| 41509480009 | U091T101   | W180'            | MWET   | 7/24/06  |
| 41509600009 | U091T102   | W75' of E150'    | WTLD   | 4/4/06   |
| 41509800003 | U091T104   | E75' OF W180'    | WTLD   | 5/13/04  |
| 41509880007 | U091T104   | W105'            | MWET   | 8/30/07  |
| 41510080003 | U091T117   |                  | SPUP   | 8/29/05  |
| 41510240005 | U091T110   | W75' OF E180'    | WTLD   | 8/16/06  |
| 41510280007 | U091T110   | W75'             | WTLD   | 7/2/07   |
| 41510320006 | U091T111   | E75' OF W150'    | WTLD   | 8/30/04  |
| 41510560002 | U091T097   | 4780 40th Ave SE | WTLD   | 3/7/08   |
| 41510720004 | U091T118   | W180'            | WTLD   | 6/18/07  |
| 41510760006 | U091T118   | E180'            | WTLD   | 6/18/07  |
| 41510840007 | U091T120   | E 1/2            | WTLD   | 12/10/07 |
| 41510840104 | U091T120   | U091T120         | WTLD   | 12/10/07 |
| 41560640008 | U091AT129  | S150'            | MWET   | 6/11/05  |
| 41560800000 | U091AT131  | S180'            | MWET   | 4/28/06  |
| 41603520004 | U092T038   | W180'            | WTLD   | 11/4/03  |
| 41610040008 | U092T001   | E180'            | UPLD   | 8/4/06   |
| 41610200000 | U092T003   | E180'            | UPLD   | 3/21/05  |
| 41610240002 | U092T003   | W75'             | SPUP   | 3/31/04  |
| 41610280004 | U092T003   | E75' of W150'    | UPLD   | 3/27/07  |
| 41610400004 | U092T005   | E180'            | NDSP   | 6/9/05   |
| 41610440006 | U092T005   | W150'            | NDSP   | 1/21/05  |
| 41610600008 | U092T006   | E 105'           | UPLD   | 3/23/10  |
| 41610680002 | U092T007   | E180'            | UPLD   | 1/5/06   |
| 41610800002 | U092T008   | W 105'           | UPLD   | 3/23/10  |
| 41611320002 | U092T013   | W180'            | NDSP   | 1/29/07  |
| 41611720000 | U092T019   | E75'             | UPLD   | 12/12/05 |
| 41611800001 | U092T019   | E180'            | UPLD   | 11/8/05  |
| 41611880005 | U092T020   | W150'            | NDSP   | 2/5/08   |
| 41612160009 | U092T023   | W75'             | UPLD   | 2/7/06   |
| 41612240000 | U092T024   | W105'            | UPLD   | 9/14/05  |
| 41612360003 | U092T025   | E150'            | UPLD   | 3/17/06  |
| 41612720009 | U092T029   | E180'            | MWET   | 8/5/03   |
| 41612760001 | U092T030   | W150'            | NDSP   | 3/2/04   |

| Folio#      | Unit/Tract | Section        | Determ | Date     |
|-------------|------------|----------------|--------|----------|
| 41613080007 | U092T033   | W 150'         | UPLD   | 12/13/07 |
| 41613400001 | U092T037   | W180'          | WTLD   | 2/17/06  |
| 41613440003 | U092T037   | W75' of E150'  | WTLD   | 3/17/06  |
| 41613760000 | U092T040   | E75'           | MWET   | 3/23/05  |
| 41613800009 | U092T041   | E150'          | MWET   | 2/5/04   |
| 41613880003 | U092T042   | W180'          | MWET   | 8/27/01  |
| 41613960004 | U092T042   | W75' OF E150'  | WTLD   | 11/22/04 |
| 41614000002 | U092T043   | W150'          | MWET   | 2/27/04  |
| 41614160007 | U092T045   | E180'          | WTLD   | 4/13/07  |
| 41614200006 | U092T075   | W150'          | WTLD   | 10/9/02  |
| 41614320009 | U092T046   | W75' OF E180'  | MWET   | 7/24/06  |
| 41614400000 | U092T047   | W150'          | WTLD   | 1/25/02  |
| 41614440002 | U092T048   | E180'          | WTLD   | 6/11/05  |
| 41614640006 | U092T050   | W180'          | WTLD   | 5/9/00   |
| 41614960003 | U092T053   | W180'          | WTLD   | 1/10/07  |
| 41615000001 | U092T053   | E150'          | WTLD   | 3/7/07   |
| 41615120004 | U092T055   | W180'          | NDSP   | 6/15/04  |
| 41615160006 | U092T056   | S300'          | NDSP   | 7/6/06   |
| 41615160006 | U092T056   | N330'          | WTLD   | 3/17/06  |
| 41615160006 | U092T056   | Front 300'     | WTLD   | 3/17/06  |
| 41615360000 | U092T059   | E180'          | WTLD   | 3/27/07  |
| 41615400009 | U092T059   | W150'          | WTLD   | 9/8/01   |
| 41615480003 | U092T060   | E75' of W150'  | WTLD   | 1/24/05  |
| 41615520002 | U092T060   | W75'           | MWET   | 8/17/05  |
| 41615880001 | U092T065   | E150'          | MWET   | 7/24/06  |
| 41616040002 | U092T066   | E150'          | WTLD   | 5/19/04  |
| 41616120003 | U092T067   | W180'          | WTLD   | 12/6/06  |
| 41616160005 | U092T067   | W75' OF E150'  | MWET   | 6/22/06  |
| 41616440000 | U092T072   | S1/2           | NDSP   | 1/5/06   |
| 41616440107 | U092T072   | N & S 1/2      | NDSP   | 12/12/05 |
| 41616600002 | U092T076   | E165'          | UPLD   | 2/20/04  |
| 41616600002 | U092T076   | W165'          | WTLD   | 2/18/04  |
| 41616680006 | U092T078   | 5ACRES         | UPLD   | 12/11/02 |
| 41616800006 | U092T081   | 5ACRES         | UPLD   | 9/22/04  |
| 41617480001 | U092T091   | E 1/2          | WTLD   | 7/6/07   |
| 41617500004 | U092T091   | W 1/2          | WTLD   | 7/6/07   |
| 41617520000 | U092T092   | E180'          | NDSP   | 8/17/07  |
| 41617560002 | U092T092   | W150'          | WTLD   | 5/8/07   |
| 41617920008 | U092T096   | E180'          | NDSP   | 11/16/04 |
| 41618040000 | U092T097   | E105' of E180' | WTLD   | 9/27/06  |
| 41618600000 | U092T103   | W180'          | NDSP   | 8/14/03  |
| 41618680004 | U092T104   | E75' of W180'  | WTLD   | 2/15/05  |
| 41618720003 | U091T104   | W150'          | WTLD   | 7/27/01  |
| 41618760005 | U092T105   | E165'          | WTLD   | 8/7/06   |
| 41619000007 | U092T109   | E105'          | WTLD   | 1/25/05  |
| 41619040009 | U092T109   | W75' OF E180'  | WTLD   | 7/27/01  |
| 41619120000 | U092T110   | W150'          | MWET   | 8/18/05  |
| 41660080005 | U092AT114  | W150'          | NDSP   | 3/31/06  |
| 41660160006 | U092AT115  | E150'          | UPLD   | 10/17/05 |
| 41660200005 | U092AT115  | W180'          | UPLD   | 5/20/05  |
| 41660200005 | U092AT115  | W180'          | UPLD   | 10/17/05 |
| 41660320008 | U092AT118  | W150'          | UPLD   | 10/17/05 |

| Folio#      | Unit/Tract | Section       | Determ | Date     |
|-------------|------------|---------------|--------|----------|
| 41660360000 | U092AT118  | E180'         | NDSP   | 1/24/06  |
| 41660520002 | U092T120   | 6ACRES        | WTLD   | 9/19/02  |
| 41660600003 | U092T122   | E105'         | NDSP   | 9/4/07   |
| 41660800007 | U092T124   |               | UPLD   | 11/4/03  |
| 41661000000 | U092T127   | E75'          | UPLD   | 10/12/04 |
| 41661040002 | U092T127   | W75' OF E150' | UPLD   | 5/19/04  |
| 41661160005 | U092T130   | W150'         | NDSP   | 10/12/04 |
| 41710440003 | U093T009   | E150'         | UPLD   | 11/4/03  |
| 41710600005 | U093T011   | W180'         | UPLD   | 5/19/04  |
| 41710720008 | U093T012   | W180'         | NDSP   | 9/21/05  |
| 41711080006 | U093T017   | E180'         | NDSP   | 1/11/05  |
| 41711120005 | U093T018   | E180'         | NDSP   | 2/12/03  |
| 41711160007 | U093T018   | W150'         | NDSP   | 5/12/04  |
| 41711160007 | U093T018   | W150'         | SPUP   | 4/26/05  |
| 41711200006 | U093T019   | E180'         | UPLD   | 3/30/05  |
| 41711240008 | U093T019   | W75' OF W150' | NDSP   | 12/8/03  |
| 41711320009 | U093T020   | E105'         | UPLD   | 4/8/04   |
| 41711440002 | U093T020   | W75'          | UPLD   | 6/12/07  |
| 41711640006 | U093T023   | E 1/2         | UPLD   | 3/31/06  |
| 41711760009 | U093T024   | E75' of W150' | NDSP   | 3/27/06  |
| 41711760009 | U093T024   | E75' OF W150' | SPUP   | 7/18/06  |
| 41711840000 | U093T025   | W180'         | NDSP   | 8/5/03   |
| 41711880002 | U093T026   | W105'         | UPLD   | 8/8/01   |
| 41712000001 | U093T027   | W75' of E150' | UPLD   | 4/19/05  |
| 41712120004 | U093T028   | E150'         | UPLD   | 9/8/01   |
| 41712200005 | U093T029   | E150'         | UPLD   | 12/15/03 |
| 41712360000 | U093T031   | E150'         | UPLD   | 8/4/06   |
| 41712600003 | U093T033   | E180'         | UPLD   | 6/29/04  |
| 41712640005 | U093T034   | E180'         | UPLD   | 9/21/05  |
| 41712840009 | U093T036   | E180'         | UPLD   | 1/28/04  |
| 41713000000 | U093T038   | W150'         | UPLD   | 1/3/05   |
| 41713040002 | U093T039   | W 150'        | UPLD   | 3/23/10  |
| 41713200004 | U093T040   | E 105'        | UPLD   | 3/23/10  |
| 41713240006 | U093T041   | W105'         | UPLD   | 4/21/04  |
| 41713360009 | U093T041   | E75' OF W180' | UPLD   | 3/18/04  |
| 41713440000 | U093T042   | E150'         | NDSP   | 3/31/06  |
| 41713600002 | U093T044   | W180'         | UPLD   | 2/10/05  |
| 41713960001 | U093T048   | W75' OF E150' | UPLD   | 12/15/03 |
| 41714120002 | U093T050   | W150'         | UPLD   | 6/26/07  |
| 41714320006 | U093T052   | W150'         | NDSP   | 1/3/05   |
| 41714440009 | U093T054   | W75'          | NDSP   | 4/16/03  |
| 41714480001 | U093T054   | E180'         | NDSP   | 9/8/01   |
| 41714680005 | U093T057   | E150'         | UPLD   | 12/19/03 |
| 41714720004 | U093T058   | W1/2          | UPLD   | 11/10/03 |
| 41714720004 | U093T058   | E1/2          | UPLD   | 1/22/04  |
| 41714840007 | U093T060   | E150'         | UPLD   | 10/24/06 |
| 41714880009 | U093T060   | W 180'        | UPLD   | 3/23/10  |
| 41714920008 | U093T061   | E75'          | UPLD   | 4/20/05  |
| 41714960000 | U093T061   | W75' OF E150' | UPLD   | 1/22/04  |
| 41715080002 | U093T062   | 5ACRES        | UPLD   | 11/22/04 |
| 41715160003 | U093T063   | W105'         | UPLD   | 7/21/03  |
| 41715360007 | U093T064   | E75'          | NDSP   | 6/15/03  |

| Folio#      | Unit/Tract | Section       | Determ | Date      |
|-------------|------------|---------------|--------|-----------|
| 41715480000 | U093T066   | W75' OF E180' | SPUP   | 1/12/05   |
| 41715520009 | U093T066   | E75' OF W150' | UPLD   | 11/20/06  |
| 41715600000 | U092T067   | 5ACRES        | UPLD   | 7/23/01   |
| 41715680004 | U093T068   | W150'         | SPUP   | 12/7/04   |
| 41715720003 | U093T069   | W 150'        | UPLD   | 3/23/10   |
| 41715760005 | U093T069   | E150'         | NDSP   | 1/28/08   |
| 41716000007 | U093T072   | E 105"        | UPLD   | 3/23/10   |
| 41716200001 | U093T073   | N105'         | NDSP   | 6/17/05   |
| 41716320004 | U093T076   | N75' of S180' | UPLD   | 5/6/05    |
| 41716560000 | U093T078   | N75' OF S180' | UPLD   | 8/29/06   |
| 41716640001 | U093T079   | S75' OF N180' | UPLD   | 1/6/05    |
| 41716640001 | U093T079   | S75' OF N180' | UPLD   | 1/11/05   |
| 41717080000 | U093T085   | S75'          | UPLD   | 4/20/06   |
| 41717200000 | U093T086   | N150'         | UPLD   | 9/11/03   |
| 41717200000 | U093T086   | N150'         | UPLD   | 10/9/06   |
| 41717640000 | U093T076   | S105'         | UPLD   | 1/28/08   |
| 41718000005 | U093T095   | W105'         | WTLD   | 7/12/02   |
| 41718200009 | U093T099   | W1/2          | UPLD   | 9/12/06   |
| 41718200106 | U093T099   | E1/2          | NDSP   | 8/22/06   |
| 41718320002 | U093T101   | S180'         | NDSP   | 11/22/04  |
| 41718320002 | U093T101   | S180'         | UPLD   | 2/22/05   |
| 41718360004 | U093T101   | N75'          | WTLD   | 2/27/04   |
| 41718400003 | U093T101   | S75' OF N150' | SPUP   | 9/29/04   |
| 41718600007 | U093T104   | S75' OF N180' | NDSP   | 1/11/05   |
| 41718760002 | U093T105   | W180'         | WTLD   | 1/3/05    |
| 41718840003 | U093T106   | W1/2          | NDSP   | 5/22/07   |
| 41718840100 | U093T106   | E1/2          | NDSP   | 6/27/07   |
| 41719160106 | U093T111   | W165'         | WTLD   | 12/4/06   |
| 41719200008 | U093T112   | W180'         | NDSP   | 11/8/04   |
| 41719240000 | U093T112   | E150'         | UPLD   | 6/19/06   |
| 41719280002 | U093T113   | W150'         | UPLD   | 1/30/06   |
| 41719600006 | U93T119    | E180'         | WTLD   | 9/19/05   |
| 41719720009 | U093T119   | E75' OF W150' | WTLD   | 4/21/03   |
| 41719760001 | U093T120   | 5ACRES        | WTLD   | 3/31/04   |
| 41719800000 | U093T121   | W180'         | WTLD   | 10/21/04  |
| 41719880004 | U093T122   | W180'         | WTLD   | 2/27/04   |
| 41720400004 | U093T128   | E 150'        | NDSP   | 1/28/08   |
| 41770880001 | U093T144   | W150'         | UPLD   | 6/18/02   |
| 41800160006 | U096T009   |               | UPLD   | 5/22/2009 |
| 41820280001 | U095T007   |               | WTLD   | 1/28/04   |
| 41820480005 | U095T012   | W150'         | WTLD   | 12/6/06   |
| 41820520004 | U095T012   | W150'         | WTLD   | 12/4/06   |
| 41821080006 | U095T023   | S180'         | MWET   | 10/19/04  |
| 41821200006 | U095T024   | S75'          | WTLD   | 8/8/06    |
| 41821720007 | U095T028   | N180'         | SPUP   | 12/7/05   |
| 41821720007 | U095T028   | N180'         | WTLD   | 2/12/04   |
| 41822000001 | U095T031   | N150'         | WTLD   | 9/9/04    |
| 41822200005 | U095T033   | S180'         | UPLD   | 5/13/04   |
| 41822720006 | U095T038   | W75' OF E150' | SPUP   | 9/23/04   |
| 41822840009 | U095T039   | E75'          | NDSP   | 7/17/08   |
| 41823080004 | U095T041   | W180'         | UPLD   | 12/18/05  |
| 41823400008 | U095T044   | W180'         | WTLD   | 7/9/03    |

| Folio#      | Unit/Tract   | Section             | Determ | Date      |
|-------------|--------------|---------------------|--------|-----------|
| 41823760007 | Hickory Wood |                     | WTLD   | 2/13/2012 |
| 41823920009 | U095T049     | W75' OF E150'       | UPLD   | 4/1/02    |
| 41824920008 | U095T057     | W75' OF E150'       | UPLD   | 11/14/02  |
| 41824960000 | U095T057     | 0' PAST CURRENT HOM | SPUP   | 8/1/05    |
| 41825040000 | U095T057     | E75' OF E150'       | UPLD   | 10/11/05  |
| 41825160003 | U095T058     | W180'               | NDSP   | 1/28/05   |
| 41825160003 | U095T058     | W180'               | SPUP   | 4/4/05    |
| 41825280006 | U095T059     | E75' OF W180'       | WTLD   | 11/12/03  |
| 41825560001 | U095T062     | E105'               | SPUP   | 11/6/03   |
| 41825800004 | U095T064     | E75' OF W150'       | SPUP   | 10/2/03   |
| 41826080001 | U095T065     | E105'               | NDSP   | 1/23/03   |
| 41826240003 | U095T067     | W 165'              | UPLD   | 12/11/07  |
| 41826440007 |              | 5190 TEAKWOOD DR    | UPLD   | 1/23/08   |
| 41826480009 | U095T070     | E75' of W180'       | UPLD   | 9/17/05   |
| 41826920006 | U095T073     | W75' OF E150'       | UPLD   | 12/28/01  |
| 41827120009 | U095T074     | E75' of E150'       | WTLD   | 1/28/05   |
| 41827160001 | U095T074     | W180'               | WTLD   | 6/5/02    |
| 41827240002 | U095T076     | W180'               | NDSP   | 12/26/03  |
| 41827320003 | U095T077     | E180'               | WTLD   | 3/18/04   |
| 41827600008 | U095T079     | W75'                | WTLD   | 1/14/02   |
| 41828400003 | U095T085     | E150'               | UPLD   | 3/18/02   |
| 41828520006 | U095T086     | E75' OF W180'       | NDSP   | 2/13/04   |
| 41828640009 | U095T087     | W75' OF E150'       | NDSP   | 11/2/04   |
| 41828640009 | U095T087     | W75' OF E150'       | UPLD   | 11/16/04  |
| 41828800001 | U095T088     | E75' OF W150'       | WTLD   | 9/13/02   |
| 41828840003 | U095T088     | W75'                | NDSP   | 10/15/02  |
| 41828840003 | U095T088     | W75'                | SPUP   | 6/15/05   |
| 41829000004 | U095T090     | W75' OF E150'       | UPLD   | 5/14/02   |
| 41829720009 | U095T096     | W150'               | UPLD   | 4/16/03   |
| 41831200009 | U095T108     | W75' of E180'       | SPUP   | 11/10/05  |
| 41831440005 | U095T110     | E150'               | WTLD   | 6/25/04   |
| 41832560007 | U095T120     | W105'               | UPLD   | 1/3/03    |
| 41832780007 | U095T124     | 5ACRES              | SPUP   | 12/1/03   |
| 41832800000 |              | Coral Wood Dr (GGE) | UPLD   | 6/13/2011 |
| 41832840002 | U095T126     | 5ACRES              | NDSP   | 5/7/03    |
| 41834110102 | U095T110     | W180'               | WTLD   | 1/13/06   |
| 41880160006 | U096T008     | N165'               | UPLD   | 11/24/04  |
| 41880360107 | U096T012     | Less S167' thereof  | UPLD   | 3/31/06   |
| 41880560004 | U096T016     | N152'               | UPLD   | 12/29/05  |
| 41880761007 | U096T019     | W365'               | UPLD   | 12/13/02  |
| 41881240006 | U096T024     | N75' OF N150'       | UPLD   | 12/6/02   |
| 41881680006 | U096T035     | W180'               | NDSP   | 6/11/07   |
| 41881760007 | U096T036     | W180'               | UPLD   | 12/29/05  |
| 41882320006 | U096T041     | E180'               | NDSP   | 2/21/06   |
| 41882840007 | U096T046     | E75' OF W150'       | WTLD   | 12/6/04   |
| 41882960000 | U096T051     | W75' OF E150'       | UPLD   | 8/14/01   |
| 41883160003 |              | 6070 BUR OAKS LN    | UPLD   | 12/26/07  |
| 41883440008 | U096T057     | E180'               | UPLD   | 8/26/03   |
| 41883760005 | U096T061     | E180'               | UPLD   | 1/11/06   |
| 41884320004 | U096T070     | E150'               | WTLD   | 7/11/07   |
| 41884560000 | U096T073     | E180'               | UPLD   | 6/9/03    |
| 41884880007 | U096T078     | E75' OF W150'       | UPLD   | 12/11/02  |

| Folio#      | Unit/Tract | Section       | Determ | Date     |
|-------------|------------|---------------|--------|----------|
| 41885360005 | U096T086   | E150'         | WTLD   | 3/31/06  |
| 41885640000 | U096T091   | W150'         | WTLD   | 9/22/03  |
| 41885720001 | U096T092   | E180'         | NDSP   | 7/15/04  |
| 41885800002 | U096T093   | E75' OF W150' | WTLD   | 8/8/06   |
| 41886640009 | U096T105   | E180'         | UPLD   | 1/22/02  |
| 41886880005 | U096T108   | W165'         | UPLD   | 12/26/01 |
| 41887000004 | U096T110   | E75' OF W150' | UPLD   | 11/21/01 |
| 41887360003 | U096T118   | E150'         | WTLD   | 10/3/06  |
| 41887840002 | U096T126   | W1/2          | UPLD   | 5/14/02  |
| 41930200007 | U097T004   | 5ACRES        | UPLD   | 2/12/04  |
| 41930480005 | U097T007   | S165'         | UPLD   | 9/26/01  |
| 41930722006 | U097T015   | E300'         | UPLD   | 7/2/01   |
| 41931340005 | U097T029   |               | UPLD   | 3/26/02  |
| 41931600004 | U097T030   | E360'         | UPLD   | 4/27/06  |
| 41931640006 | U097T031   | S150'         | SPUP   | 12/16/03 |
| 41932070002 | U097T035   | E330'         | UPLD   | 5/23/02  |
| 41932280009 | U097T038   | S180'         | UPLD   | 8/19/03  |
| 41932360000 | U097T039   | N75' OF S150' | UPLD   | 6/7/02   |
| 41933160005 | U097T048   | E150'         | UPLD   | 3/26/02  |
| 41933200004 | U097T048   | W180'         | NDSP   | 9/20/05  |
| 41933280008 | U097T050   |               | UPLD   | 1/28/08  |
| 41933361008 | U097T052   | W1/2          | UPLD   | 5/14/02  |
| 41933560003 | U097T054   | W75'          | WTLD   | 9/25/06  |
| 41933840008 | U097T057   | E180'         | UPLD   | 12/26/01 |
| 41933880000 | U097T057   | W75'          | UPLD   | 10/11/04 |
| 41934480001 | U097T064   | W180'         | UPLD   | 4/8/03   |
| 41934760006 | U097T068   | E150'         | UPLD   | 5/27/08  |
| 41934960000 | U097T071   |               | UPLD   | 1/28/08  |
| 41935080002 | U097T073   | W 1/2         | NDSP   | 10/4/05  |
| 41935280006 | U097T075   | E75' OF W150' | WTLD   | 6/19/06  |
| 41935520009 | U097T078   | W150'         | SPUP   | 4/7/04   |
| 41935680004 | U097T081   | E150'         | UPLD   | 11/1/05  |
| 41935960009 | U097T084   | E75' OF W180' | UPLD   | 2/20/03  |
| 41936080001 | U097T086   | W180'         | UPLD   | 4/27/06  |
| 41936120000 | U097T086   | E150'         | UPLD   | 12/26/01 |
| 41936240003 | U097T088   | E150'         | WTLD   | 10/7/04  |
| 41936320004 | U097T089   | E75'          | UPLD   | 2/6/02   |
| 41936440007 | U097T090   | LESS N150'    | UPLD   | 2/1/05   |
| 41936600009 | U097T093   | W150'         | WTLD   | 6/5/01   |
| 41937360005 | U097T102   | Standing Oaks | UPLD   | 3/14/06  |
| 41937760003 | U097T108   | W105'         | WTLD   | 11/22/02 |
| 41938080009 | U097T112   | E180'         | UPLD   | 11/7/02  |
| 41938320002 | U097T114   | E180'         | UPLD   | 6/28/04  |
| 41938440005 | U097T116   | W165'         | UPLD   | 11/10/03 |
| 41938760002 | U097T121   | E165'         | UPLD   | 3/26/02  |
| 41939360003 | U097T128   | E150'         | NDSP   | 7/15/04  |
| 41940040008 | U097T139   | W75' OF E180' | UPLD   | 11/27/01 |
| 41940320003 | U097T142   | E150'         | UPLD   | 3/26/02  |
| 41940560009 | U097T145   | E75' OF W180' | MWET   | 7/11/01  |
| 41940740007 | U097T146   | W170'         | WTLD   | 5/25/07  |
| 41940880006 | U097T148   | E165'         | MWET   | 6/15/03  |
| 41941080009 | U097T151   | 3ACRES        | UPLD   | 8/22/02  |